

iOS firmware update for I-THERMIC


clim8 firmware update
Fixes iOS compatibility issues



REQUIREMENTS:


- 1.** This update is for iPhone 6, 6S and SE (1st Gen). It applies to the core8 (battery) module FW 3.0.0.
- 2.** For users with an iPhone 7 or newer, and where compatibility issues persist, an older device is required to first complete this update prior to use. For iOS users who also have an Android device (OS 5.0 or higher), the firmware update can be completed using the Android device. Once installed, it will be ready for use with your iOS device.
- 3.** For users with an iPhone 7 or newer, and where compatibility issues persist, an older device is required to first complete this update prior to use. For iOS users who also have an Android device (OS 5.0 or higher), the firmware update can be completed using the Android device. Once installed, it will be ready for use with your iOS device.
- 4.** Before installing the update, please reset the device to factory settings. This is done by snapping the core8 module onto the shirt then pressing and holding the power button for 7 seconds until the LED is flashing.
- 5.** Follow the step-by-step guide in this document.

1.




Open the App store and search for « clim8 »

2.




Open the app and click on “Start”

3.



Select the sign in method of your choice


4.



Create your profile


Note: Make sure your app is up to date v3.0.1 or more

5.




Enable Bluetooth and Location permissions

6.



Click on "Add your clim8 device"

7.



Select "T-shirt" from the category

8.



- a. Plug the core8 module on to the baselayer.
- b. Turn the core8 module ON

9.



After clicking on "Start", the app will start the Bluetooth scan

10.




Wait until your device is paired.

Notes:

- Sometimes, turning the core8 on/off can help speed up the connection.
- Old OS versions might lead to longer scanning time.

11.



The app will search for the update.

Note:

Make sure your internet connection is fast and stable

12.



Click on "Update"

Note:

Make sure your internet connection is fast and stable


13.



Wait until your core8 module is being updated.

*Note:
30 sec to 1min, depending
on internet connection
and OS version*

14.



Once updated, click on "Finish" to finalize the procedure.


15.



Now you're good to go. You can click on "close".

*Note:
Do NOT go further than this
stage for smoother
experience if you are making
this update for your iPhone*

16.



Close the app



**The Firmware is
now up-to-date.**

**Your I-THERMIC
baselayer
is ready for use.**

